Status of Existing Facility Instruments

Takashi Hattori (Instrument Division, Subaru Telescope)

Subaru User's Meeting 2020 (3/3/2021)



♦ On-axis dome flat lamp



- ♦ On-axis dome flat lamp
 - ♦ better flatness compared to the conventional four-lamp system
 - started regularly using the on-axis dome flat lamp from Feb. 2021 observing run



sky value after flat-fielding



on-axis

conventional

♦ issues

- \diamond a sensor hitting the filter-frame
 - a sensor was found to be hitting the filter frame and preventing HSC-i2 filter to be removed from the camera
 - almost no filter exchange in the January, 2021 observing run
- \diamond collision signal from CCB
 - multiple collision signals from POpt2, WFC, and FEU on 1/10/2021
 - a cable from the CCB controller touched the surface of the box, which caused fake collision signals
 - half night was lost



♦ issues

- \diamond a sensor hitting the filter-frame
 - a sensor was found to be hitting the filter frame and preventing HSC-i2 filter to be removed from the camera
 - almost no filter exchange in the January, 2021 observing run
- \diamond collision signal from CCB
 - multiple collision signals from POpt2, WFC, and FEU on 1/10/2021
 - a cable from the CCB controller touched the surface of the box, which caused fake collision signals
 - ♦ half night was lost





"Collision Collection Box" on POpt2

♦ issues

- ♦ CCD readout time (January, 2020)
 - ♦ it suddenly started showing large variation of readout time

 \Leftrightarrow normally, it is ~18.5 seconds



♦ issues

- ♦ CCD readout time
 - ♦ resolved by increasing the "nice value" and priority of Messia server process

♦ it has been stable after March, 2021 observing run



LGS/AO188

- ♦ Laser Guide Star Upgrade
 - ♦ installation of the major components started in February, 2021
 - ♦ continues in March, April
 - ♦ first on-sky test in April-May
 - ♦ "P19 Minowa et al." for details





LGS/AO188

- TBAD (Transponder-Based Aircraft Detector)
 - ♦ system to detect airplanes and shut off the LGS automatically

TBAD on the telescope

TBAD and TSIM



LGS/AO188

- TBAD (Transponder-Based Aircraft Detector)
 - \diamond validation
 - ♦ Maunakea fly-over test
 - \diamond attempted on 2/20/2021 but was postponed due to bad weather
 - ♦ planned on 3/6/2021
 - ♦ 6 months operation with spotter



TBAD fly-over test plan

LGS/A0188

- ♦ AO188 related upgrades
 - ♦ new Deformable Mirror
 - ALPAO DM3228 (64x64)
 - ♦ arriving in this summer
 - ♦ Near Infrared Pyramid WaveFront Sensor
 - $\ensuremath{\circledast}$ test and installation in this year
 - ♦ Nasmyth Beam Switcher
 - In final design by AAO is still ongoing
 - fabrication cost is being requested
 - ♦ ULTIMATE-START
 - & Grant-in-Aid project (PI:Akiyama)
 - ♦ Laser Tomographic AO with 4 LGS
 - ♦ o28 Ono et al., p02 Akiyama et al.



ALPAO DM3228



LGS/A0188

- ♦ new Real Time System (RTS)
 - ♦ replace the current RTS computer
 - NGS mode validation was completed
 - LGS mode validation is not yet completed
 - ♦ stability issues after software upgrade, laser upgrade works, etc.
 - ♦ bug fixes
 - \diamond concerns on possible damage on the aging deformable mirror (~15 years old)
 - ♦ during the software development phase
 - \diamond discussions with the DM manufacture
 - ♦ possible development of safety mechanism
 - ♦ advanced control
 - * predictive control, 2kHz loop, joint control with AO188 and SCExAO
 - * difficulty in continuing those developments with the current DM
 - \rightarrow focus on the development with the new ALPAO DM (under discussion)

LGS/A0188

- ♦ hardware issues in 2020
 - ♦ replacements
 - ADC Hall sensor (to be done)
 - * XPS controller (for image rotator, LOWFS)
 - temperature monitoring unit
 - SMC chiller parts
 - ♦ aging of hardwares is now an ongoing issue with AO188...
 - ♦ continue to replace and upgrade the subcomponents

IRCS

- ♦ Some issues with the detector electronics (same as last year...)
 - ♦ unstable behavior (especially after instrument exchanges)
 - ♦ glow-pattern
 - can be suppressed by changing voltage settings
 - ♦ test is still ongoing



- ♦ new user filters
 - ♦ NB 1984 (already installed)
 - ♦ NB 1189 (possible installation in this summer)

HDS

- ♦ No major issue/activity
- ♦ improvement for image-slicer replacement procedure
 - ♦ new handles and fall-protection of screws





MOIRCS

- LightSmyth high efficiency grism
 - ♦ Grant-in-Aid (Kakenhi) project (PI:Kodama)
 - $\Leftrightarrow\,$ J- and H-band grisms
 - \diamond assembly and laboratory tests in early 2020



MOIRCS

- LightSmyth high efficiency grism
 - \diamond first light in July, 2020



 \diamond has been used for open-use observation

MOIRCS

♦ Hibernation

- following the successful commissioning of SWIMS
 p10 Konishi et al.
- \Leftrightarrow from S21A to S22B
- \diamond minor activities during the hibernation
 - \diamond replacement of grisms and filters
 - * improvement of K-band VPH grism
 - $\diamond\,$ to remove large spatial shift and tilt
 - ♦ depends on budget availability
 - ♦ resolve software issues

COMICS

- ♦ Decommissioned after S20A
 - ♦ pictures from the last observing night, 7/30/2020



https://subarutelescope.org/en/news/topics/2020/08/19/2893.html



FOCAS

- No major issue/activity on the instrument
- Trouble with the laser cutter (MOS mask cutting)
 - ♦ happened in November, 2019
 - \diamond laser-diode current-driver was replaced in January, 2020



Summary 2020

Prime Focus

HSC

On-Axis dome flat, FEU and readout issues

Nasmytl	h
AO188	LGS upgrade, various upgrades on NsIR, hardware issues
IRCS	Issues with detector electronics, new user filters
HDS	No major issue/activity

Cassegrain

MOIRCS	LightSmyth grisms, hibernation
COMICS	Final light on 7/30/2020
FOCAS	Laser cutter trouble

