

Stray light from the encoder of POpt2 rotator

December 26, 2019 (updated on July 8, 2020)

- \bullet A light leak from the encoder of instrument rotator causes stray light on HSC images in the wavelength range of z and Y bands.
- The stray light appears a similar pattern at every 45° of the rotator angle (InR) because eight of the encoder heads are arranged at 45° intervals along the outer circumference.
- Shielding plates were installed in November 2017. The stray light level was significantly reduced though the effect still appears on z- and Y-band images.
- \bullet Y-band images taken with the dome closed before and after the shielding plates were installed :




Apr 2017, Y-band, 60 sec, $InR = 0^{\circ}$




Nov 2019, Y-band, 200 sec, $InR = 0^{\circ}$

 \bullet i2- and z-band images taken with the dome closed after the shielding plates were installed:




Dec 2019, *i*2-band, 200 sec, $InR = 0^{\circ}$




Nov 2019, z-band, 200 sec, $InR = 0^{\circ}$


 \bullet Y-band images with 60 sec exposure in 2017 Apr (before the shielding plates were installed) :




 \bullet z-band images with 200 sec exposure in 2019 Nov (after the shielding plates were installed) :




• The stray light is also collected on the CCDs during the readout process.



The count profile of overscan-subtracted bias data in the Y band



The count profile of overscan-subtracted bias data in the z band



The count profile of overscan-subtracted bias data in the g band