

# Inspection of HSC images after vacuum leak accident on Aug 3, 2023

T.Terai (Subaru Telescope)

August 11, 2023

- HSC's CCD dewar experienced a vacuum leak accident when vacuuming was restarted after HSC was installed into POpt2 at the TUE floor on August 3, 2023.
- Comparing the domeflat images between the consecutive two HSC runs in June and August, no changes were seen in all CCDs except for the four ones with DET-ID = 040, 041, 042, and 065.
- A shadow spot previously located on CCD #042 was likely to move to CCD #040.

